

Phos Etch

A concentrated phosphoric acid solution containing inhibitors, solvents and emulsifiers.



Acid Cleaner:

Used for the etching and degreasing of galvanized or mild steel prior to painting.

Preparation

Wet surface thoroughly with fresh water prior to acid etching.

Application

- Use 1:4 with water and apply with a paint brush by working from the bottom upwards.
- Leave on until effervescence ceases and flush off with a strong jet of water.
- Practical coverage: 8-10m²/L

Precautions

Corrosive to skin. Wear gloves and protective clothing. Avoid contact with eyes and skin. If skin contact should occur, rinse well with water. For eye contact rinse well with water and call a doctor.

Handling, Safety & Storage

PPE should be a requirement with all chemically formulated products as precaution, dust mask, gloves and apron.

Disclaimer

This information relates only to the specific material designated and may not be valid for such material used in combination with any other materials or in any other process. Such information is, to the best of Flowcrete's knowledge and belief, accurate and reliable as at the date of issue. However no warranty, guarantee or representation is made as to its accuracy, reliability or completeness. It is the user's responsibility to satisfy himself as to the suitability.